

Oil Field Environmental Incident Summary

Incident: 20150319101009 **Date/Time of Notice:** 03/19/2015 10:10

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: EN-HERMANSON- LE-155-93-3501H-8

Field Name: ROBINSON LAKE

Well File #: 28860

Date Incident: 3/19/2015 **Time Incident:** 00:30

Facility ID Number:

County: MOUNTRAIL

Twp: 155

Rng: 93

Sec: 35

Qtr:

Location Description:

Submitted By: Henry Jason

Received By:

Contact Person: Jason Henry
3015 16th Street SW, Suite 20
Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.2 Mile

Distance Nearest Water Well: 0.2 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	10	Barrels	10	Barrels	10	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 8/10/2015

Clean Up Concluded: 4/7/2015

Risk Evaluation:

The source of the release was secured immediately upon discovery, and two vacuum trucks began recovering the released produced water.

Areal Extent:

N/A - the release remained on the location.

Potential Environmental Impacts:

The release occurred above ground and remained on the location. Vacuum trucks were utilized to recover as much of the released produced water as practicable, and a front end loader was utilized to excavate the impacted soil.

Action Taken or Planned:

Vacuum trucks were utilized to recover as much of the released produced water as practicable, and a front end loader was utilized to excavate the impacted soil. The excavated soil was stockpiled on-site in a three-sided bin to await proper disposal.

Wastes Disposal Location: At a properly permitted disposal facility.

Agencies Involved:

Updates

Date: 3/19/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to valve/piping connection leak, remained on location within the diking according to the report. NDIC retains oversight.