

# Oil Field Environmental Incident Summary

**Incident:** 20150506143342      **Date/Time of Notice:** 05/06/2015 14:33

**Responsible Party:** ENDURO OPERATING, LLC

**Well Operator:** ENDURO OPERATING, LLC

**Well Name:** BEARD 2

**Field Name:** NORTHEAST FOOTHILLS

**Well File #:** 8462

**Date Incident:** 5/4/2015      **Time Incident:** 15:00

**Facility ID Number:**

**County:** BURKE

**Twp:** 161

**Rng:** 91

**Sec:** 7

**Qtr:**

**Location Description:**

**Submitted By:** Scott Hunskor

**Received By:**

**Contact Person:** Scott Hunskor  
777 MAIN STREET  
SUITE 800  
FORT WORTH, TX 76102

**General Land Use:** Cultivated

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	5	Barrels	5	Barrels	5	barrels
<b>Brine</b>	1	Barrels	1	Barrels	1	barrels

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 10/6/2015

**Clean Up Concluded:** 5/8/2015

**Risk Evaluation:**

none

**Areal Extent:**

20 x 20

**Potential Environmental Impacts:**

none

**Action Taken or Planned:**

patch flow line and shut in well and replace with new flow line

**Wastes Disposal Location:** PDI

**Agencies Involved:**

**Updates**

---

**Date:** 5/7/2015    **Status:** Inspection

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location at 15:00. 47 degrees F, mostly cloudy, NW wind 15-25 mph. Observed the area and took photographs. The well pad is surrounded by cultivated cropland which slopes toward the east and south. The release appeared to have occurred on the pipeline that runs to the pumpjack north of the well pad. Approximately 50' north of the pumpjack, soil had been excavated from the field. The excavation was approximately 10' wide by 30' long by 8' deep and showed the exposed pipeline and its repair. Northwest of the excavation hole, topsoil had been scraped to a depth of 2-3 inches in an area approximately 40' x 50'. On the well pad south of the pumpjack was a pile of impacted soil surrounded by an earthen berm. The soil had become saturated with rain water and released petroleum products on to the pad and into the water standing within the berm surrounding the pile. Bottom of the excavation still had impacts noted, and impacts were remaining on well pad within impacted pile. More followup needed.

---

**Date:** 5/7/2015    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

---

**Date:** 4/14/2016    **Status:** Inspection

**Author:** Wax, Pete

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On site 09:50. Cloudy, 51 degrees, 5 mph wind from the west. Nearest water 150 meters to the southeast. Work crew on site digging up flow line at previous spill location, as the line is now plugged. Site looks clean, and fill soil is free from petroleum odor or staining. Need to follow-up to ensure that the agricultural field is reshaped correctly. Off site 10:05.

---

**Date:** 7/26/2016    **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

7/26/2016 at 10:45, on location. Wheat field planted around wellpad. To the north, wheat is growing through the incident area. No visible staining. No further follow-up required at this time.