

Oil Field Environmental Incident Summary

Incident: 20160412112310 **Date/Time of Notice:** 04/12/2016 11:23

Responsible Party: PETRO HARVESTER OPERATING COMPANY, LLC

Well Operator: PETRO HARVESTER OPERATING COMPANY, LLC

Well Name: BUSCH 2 - 5

Field Name: PORTAL

Well File #: 18899

Date Incident: 4/12/2016 **Time Incident:** 06:30

Facility ID Number:

County: BURKE

Twp: 163

Rng: 92

Sec: 5

Qtr:

Location Description: Lot 2 - 660 FNL & 1980 FEL

Submitted By: Gary Watson

Received By:

Contact Person: Mark Bonnie
103 1st Av. NE

Mohall, ND 58761

General Land Use: Cultivated

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil					0	barrels
Brine	4	Barrels	4	Barrels	4	barrels

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 4/22/2016

Clean Up Concluded: 4/14/2016

Risk Evaluation:

No explosive or immediate health hazard risk. All released fluids contained within steel containment system.

Areal Extent:

Contained within steel containment system.

Potential Environmental Impacts:

No impact to surface water, groundwater or cultivated soils. All released fluids were contained with the steel containment system

Action Taken or Planned:

NDIC Field Representative Jim Potts was notified telephonically. Released fluids will be vacuumed-up and disposed in saltwater disposal well. Affected facility site soil will be scraped up, collected and hauled to an approved disposal facility. All valves on equalizing system will be inspected for corrosion.

Wastes Disposal Location: An approved disposal facility.

Agencies Involved:

Updates

Date: 4/12/2016 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained within diking according to the report. NDIC retains oversight.