

General Environmental Incident Summary

Incident: 3594 **Date/Time Notice:** 12/30/2014 1901 **DEM Incident No:**
Responsible Party: J5 Transport
Date Incident: 12/30/2014 **Time Incident:** 1900 **Duration:** 1 minutes
County: Morton **Twp:** 139 **Rng:** 85 **Sec:** 14 **Qtr:**
Lat: 46.85406 **Long:** -101.38310 **Method:** Interpolation from map
Location Description: 1309 N 8th St. New Salem

Submitted By: Paul Kramer **Affiliation:** Missouri Valley Petroleum
Address: 1722 Mandan Ave
City: Mandan **State:** ND **Zip:** 58554

Received By:

Contact Person: Paul Kramer
1722 Mandan Ave
Mandan, ND 58554

Distance Nearest Occupied Building: 100 Feet **Release Contained:** Yes

Type of Incident: Hose Nozzle seal malfunction

Description of Released Contaminant: E10 Gasoline

Volume Spilled: 80.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

Driver was filling underground gasoline tank and when the tank got to 90% full the tank flapper valve closed like it was supposed to and the nozzle on the hose that connects to the truck failed to seal properly.

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

None

Action Taken or Planned:

Spill was neutralized with a surface washing agent PetroXg3.

Wastes Disposal Location: The spill was neutralized with a surface washing agent called PetroXg3. No waste was generated.

Agencies Involved: NDDDES

Updates

Date: 12/30/2014 **Status:** Reviewed - Follow-up Required

Author: Washek, Sandi

Updated Volume:

Notes:

No material came off the concrete pad, and no water was impacted. All material was cleaned up. Inspect to confirm cleanup.

Date: 1/5/2015 **Status:** Inspection

Author: Espe, Brady

Updated Volume:

Notes:

I arrived at the site at 12:00 p.m. and departed the site at 12:48 p.m. It was snowing, with winds from the southeast at 10 mph with a temperature of -5°F. Talked to rep from the company reporting the spill; he indicated that the spill occurred at the Cenex station along the interstate north of New Salem. I also talked to an employee at the gas station who indicated the spill occurred on the south side of the property and the cleanup crew showed up the same day to clean up the spilled gasoline. The underground tanks are located on the south side of the diesel pumps. The gas flowed south towards the restaurant and then west toward the ditch. I walked around the area south of the pumps and in the ditch area. There is a small covering of fresh snow; the area also has ice in spots under the snow. Could not smell any gasoline; the spill appears to have been cleaned up. No further followup needed at this time. 46.858722; -101.416972