RECEIVED
JAN 30 2025
BY:

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	8093	A. BUILDING: 01 - MAIN BUILDING B. WING	01/21/2026

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
MAPLE VIEW MEMORY CARE OF MINOT	2805 ELK DR MINOT, ND 58701

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
K 000	INITIAL COMMENTS This survey used the 2012 edition of NFPA 101, Life Safety Code, Chapter 32 New Residential Board and Care Occupancies (Large) and Chapter 33 Existing Residential Board and Care Occupancies (Large), in compliance with NDAC 33-03-24.2. The findings that follow demonstrate noncompliance with these standards. The facility was located in a one-story building of Type V (000) fully sheathed construction with a NFPA 13 wet and dry automatic fire sprinkler system. Additions of Type V (000) construction were added to the Great Room and the Kitchen in 2019. The additions were surveyed using Chapter 32. Resident evaluation determined a Slow level of evacuation difficulty. The E-Score was 2.57.	K 000		
K 251	MANUAL FIRE ALARM General. A fire alarm system in accordance with Section 9.6 shall be provided, unless all of the following conditions are met: (1) The facility has an evacuation capability of prompt or slow. (2) Each sleeping room has exterior exit access in accordance with 7.5.3. (3) The building does not exceed three stories in height. 33.3.3.4.1 This State Licensing Rule is not met as	K 251		

North Dakota Health and Human Services

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
	8093	A. BUILDING: 01 - MAIN BUILDING B. WING _____	01/21/2026

NAME OF PROVIDER OR SUPPLIER	STREET ADDRESS, CITY, STATE, ZIP CODE
MAPLE VIEW MEMORY CARE OF MINOT	2805 ELK DR MINOT, ND 58701

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
K 251	Continued From page 1 evidenced by: A fire alarm system in accordance with section 9.6 shall be provided. 33.3.3.4.1. A fire alarm system required for life safety shall be installed, tested, and maintained in accordance with the applicable requirements of NFPA 70, National Electrical Code and NFPA 72, National Fire Alarm and Signaling Code. 9.6.1.3. 2010 NFPA 72, 14.1.1 The facility failed to test the fire alarm system as required. On 01/21/2026, review of fire alarm system test records indicated the most current fire alarm system annual test was conducted on 05/14/2024 exceeding the required annual testing requirement. Failure to test and maintain the fire alarm system in accordance with NFPA 72 increases the risk of death or injury due to fire. This deficiency affected one (1) of one (1) fire alarm system. The fire alarm system serves the entire facility.	K 251	**K251- Fire Alarm System** Maple View will have the annual fire alarm system tested on January 27, 2026 done by New Vision. It will be scheduled annually. The inspection of the fire alarm system will be scheduled with New Vision to assure the inspection is completed to meet the requirements. Verification of this inspection will be sent upon completion. The Life Safety Inspection Checklist will be monitored by the Maple View's Maintenance Manager to ensure inspection is completed annually. The completion of the inspection of the fire system will be completed on January 27, 2026. the inspection will be done annually going forward.	