

Oil Field Environmental Incident Summary

Incident: 20131207190332 **Date/Time of Notice:** 12/07/2013 18:34

Responsible Party: Baytex Energy USA, LTD

Well Operator: BAYTEX ENERGY USA LTD

Well Name: GORDON HALL 29C-3-1H

Field Name: PLUMER

Well File #: 16725

Date Incident: 12/7/2013 **Time Incident:** 04:30

Facility ID Number:

County: DIVIDE

Twp: 161

Rng: 98

Sec: 29

Qtr:

Location Description:

Submitted By: Joe Irvin

Received By:

Contact Person:

600 17TH ST STE 1600 SOUTH
DENVER, CO 80202-5419

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Miles

Distance Nearest Water Well: 1 Miles

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	barrels	0.75	barrels		
Brine	1	barrels	0.75	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Low

Areal Extent:

Potential Environmental Impacts:

Minimal due to frozen ground and quick cleanup

Action Taken or Planned:

Well promptly shut in and oil absorbent material was placed to stop spread of spill. Cleanup crew, vacuum truck and backhoe were mobilized to remove contaminated soil.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved:

Updates

Date: 12/9/2013 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident report, this spill remained on location. NDIC retains oversight.