

# Oil Field Environmental Incident Summary

**Incident:** 20131227192325      **Date/Time of Notice:** 12/27/2013 19:17

**Responsible Party:** MBI OIL & GAS, LLC

**Well Operator:** MBI OIL & GAS, LLC

**Well Name:** JELLESED SWD 1

**Field Name:** BLUE BUTTES

**Well File #:** 1167

**Date Incident:** 12/26/2013      **Time Incident:** 15:30

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 151

**Rng:** 95

**Sec:** 6

**Qtr:**

**Location Description:**

**Submitted By:** Tara DeJoseph

**Received By:**

**Contact Person:**

PO BOX 7

BELFIELD, ND 58622-0007

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** Unknown

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>
<b>Oil</b>	2	barrels	0	barrels
<b>Brine</b>	0	barrels	0	barrels
<b>Other</b>	0	barrels	0	barrels

**Followup**      **Units**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

**Areal Extent:**

5 gallon spray outside of berm area on snow

**Potential Environmental Impacts:**

**Action Taken or Planned:**

Valves shut to stop leak. Cleanup performed by Absorbent Solutions, Badlands HydroVac & MBI

**Wastes Disposal Location:** MBI Knudston SWD and Indians Hills Disposal

**Agencies Involved:**

**Updates**

---

**Date:** 12/30/2013 **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release from a valve or piping leak on location, sprayed off location, according to the report. Followup is necessary.

---

**Date:** 12/31/2013 **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

13:14, on location. Met with report contact, who indicated location of spray outside berm was on north side by the unloading hookups. Yellow stain visible outside of metal tank berm, as well as around the unloading hookups; however, no stain visible off the site in field to north. Few yellow spots on south side of site as well, but also no stain visible in field further to south. Cleanup company's hydrovac truck had broken down so cleanup was not complete, but no impact off of site grounds found.