

Oil Field Environmental Incident Summary

Incident: 20140125134538 **Date/Time of Notice:** 01/25/2014 13:32
Responsible Party: Burlington Resources
Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Name: CHUCKWAGON 21-15MBH
Field Name: SAND CREEK **Well File #:** 20528
Date Incident: 1/24/2014 **Time Incident:** 15:00 **Facility ID Number:**
County: MCKENZIE **Twp:** 153 **Rng:** 97 **Sec:** 15 **Qtr:** NW NW
Location Description: adjacent to the south east side of the pad

Submitted By: Lewis Schoenberger **Received By:**
Contact Person: Lewis Schoenberger
PO BOX 51810
MIDLAND, TX 79710-1810

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Miles
Distance Nearest Water Well: 0.5 Miles

Type of Incident: Fire

	Release Contained in Dike: No				Reported to NRC: No	
	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels		
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 8/3/2016 **Clean Up Concluded:** 3/12/2014

Risk Evaluation:

Areal Extent:
approximately 15 feet by 20 feet

Potential Environmental Impacts:

Action Taken or Planned:

The fire was extinguished.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 1/27/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to fire on location, was not contained on location. Followup is necessary.

Date: 1/29/2014 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

When I arrived at the site the temperature was 21°F, with a wind from the northwest at 20 mph. The spill report indicated southeast side; however, the flare is on the northeast side of pad. I walked around the field to east of flare and did not see any oil. The vegetation was burned on the side slope of dike to edge of field. I do not see any other issues at this time. No follow-up inspection is required at this time.