

Oil Field Environmental Incident Summary

Incident: 20140215160420 **Date/Time of Notice:** 02/15/2014 15:56

Responsible Party: HRC Operating, LLC

Well Operator: HRC OPERATING, LLC

Well Name: QUARNE 2-21-16H

Field Name: STRANDAHL

Well File #: 26084

Date Incident: 2/15/2014 **Time Incident:** 04:00

Facility ID Number:

County: WILLIAMS

Twp: 157 **Rng:** 102 **Sec:** 21 **Qtr:**

Location Description: Contiguous to well pad to south. Fine spray from pressure relief device.

Submitted By: Tristan Walker

Received By:

Contact Person: Tristan Walker
1801 CALIFORNIA STREET
SUITE 3500
DENVER, CO 80202

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1 Miles

Distance Nearest Water Well: 1 Miles

Type of Incident: Treater Popoff

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	barrels	0.5	barrels	0.5	barrels
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

n/a

Inspected:

Written Report Received: 11/27/2015

Clean Up Concluded: 2/21/2014

Risk Evaluation:

none

Areal Extent:

125 x 40

Potential Environmental Impacts:

Fine mist to snow.

Action Taken or Planned:

2/16/2014 - Cleanup of impacted snow offsite will be completed and moved to well pad then disposed week of 2/17.

Wastes Disposal Location: Authorized E&P Landfill or Injection if liquid waste.

Agencies Involved:

Updates

Date: 2/17/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from treater popoff sprayed off location. Followup is necessary.

Date: 2/20/2014 **Status:** Inspection

Author: Miller, Adam

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Area to south of road has been cleaned up, but area between road and dirt strip to east of pad still needs to be addressed. Met with company contact and showed him where work needs to be done. Contact stated he will get the contractor on it ASAP.

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site 5:56pm, the weather was sunny with wind out of the SE at 20 mph. Observed all the ditches and surrounding areas were well vegetated, with the plants showing no stress. The area of concern to the south had been reseeded, and the ditch area had storm water protection in place. No additional followup needed.