

Oil Field Environmental Incident Summary

Incident: 20140215191507 **Date/Time of Notice:** 02/15/2014 17:57

Responsible Party: R360 WILLISTON BASIN, LLC

Well Operator: R360 WILLISTON BASIN, LLC

Well Name: L.E. Johnson 1

Field Name: TYRONE

Well File #: 12167

Date Incident: 2/15/2014 **Time Incident:** 24:00

Facility ID Number:

County: WILLIAMS

Twp: 156

Rng: 101

Sec: 24

Qtr:

Location Description: Offload Transfer Pump Location

Submitted By: Adrian Trim

Received By:

Contact Person: Adrian Trim

3 Waterway Square Place, Suite 110

The Woodlands, TX 77380

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1 Miles

Distance Nearest Water Well: 1 Miles

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No

Reported to NRC: Unknown

| | Spilled | Units | Recovered | Units | Followup | Units |
|--------------|----------------|--------------|------------------|--------------|-----------------|--------------|
| Oil | 0 | barrels | 0 | barrels | | |
| Brine | 10 | barrels | 10 | barrels | 10 | barrels |
| Other | 0 | barrels | 0 | barrels | | |

Description of Other Released Contaminant:

NA

Inspected:

Written Report Received: 3/6/2014

Clean Up Concluded: 2/20/2014

Risk Evaluation:

No immediate risk.

Areal Extent:

150

Potential Environmental Impacts:

soils and stormwater

Action Taken or Planned:

valves shut, tank emptied, vacuum truck utilized, supersucker utilized, impacted soils scraped up with skidsteer. Berm will be constructed tomorrow by facility personnel

Wastes Disposal Location: Prairie Disposal LLC, Tioga, ND

Agencies Involved:

Updates

Date: 2/17/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve or piping leak, was not contained on location. Followup is necessary.

Date: 2/20/2014 **Status:** Inspection

Author: Miller, Adam

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Location is a SWD. Brine water flowed from a treatment building, across the pad, and stopped on the road, right next to the turnout of the pad. Contaminated topsoil was scraped up and disposed of. Brine water did not make it into the ditch. Company has since built a berm around the treatment building to prevent future occurrences from escaping the facility.