

Oil Field Environmental Incident Summary

Incident: 20140810233526 **Date/Time of Notice:** 08/10/2014 23:35

Responsible Party: RIM OPERATING, INC.

Well Operator: RIM OPERATING, INC.

Well Name: HMU 9-34XHR

Field Name: HOFFLUND

Well File #: 7594

Date Incident: 8/9/2014 **Time Incident:** 16:00

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 95

Sec: 9

Qtr:

Location Description:

Submitted By: Troy Johnson

Received By:

Contact Person: Troy Johnson
5 INVERNESS DRIVE EAST
ENGLEWOOD, CO 80112

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	270	Barrels	210	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Not Applicable

Areal Extent:

Potential Environmental Impacts:

Not Applicable. The spill was contained in the tank dike area and the standing fluid was sucked up the same day.

Action Taken or Planned:

The spill was contained within the tank dike area. The open tank valves were isolated. A vacuum truck sucked up the spilled fluid and put it into one of the other tanks on location. A wash down truck and crew will be out Monday to wash down and finish cleaning the affected area.

Wastes Disposal Location: The fluid will be processed on location.

Agencies Involved: I left a phone message with NDIC Inspector Tamara Cook.

Updates

Date: 8/11/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank leak, remained on location within the diking according to the report. NDIC retains oversight.