

Oil Field Environmental Incident Summary

Incident: 20140814152325 **Date/Time of Notice:** 08/14/2014 15:23

Responsible Party: OASIS PETROLEUM NORTH AMERICA LLC

Well Operator: OASIS PETROLEUM NORTH AMERICA LLC

Well Name: CASPIAN 5693 43-11H

Field Name: ALGER

Well File #: 21048

Date Incident: 8/14/2014 **Time Incident:** 10:00

Facility ID Number:

County: MOUNTRAIL

Twp: 156

Rng: 93

Sec: 11

Qtr:

Location Description: Treater upset, pushed approx. 1/2 bbl of oil out of the flare stack. Oil misted west into hayfield approx. 80 yds.

Submitted By: Jared Iverson

Received By:

Contact Person: Jared Iverson
1001 FANNIN STE 1500
HOUSTON, TX 77002

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	21	Gallons			0.25	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/9/2016

Clean Up Concluded: 11/26/2014

Risk Evaluation:

None

Areal Extent:

20' X 80 yds.

Potential Environmental Impacts:

None

Action Taken or Planned:

Oil dump valve was repaired

Wastes Disposal Location: Material will be treated on site.

Agencies Involved:

Updates

Date: 8/15/2014 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas outside of the secondary containment. Followup is necessary.

Date: 10/16/2014 **Status:** Inspection

Author: Wax, Pete

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site 8:50; off site 9:15, wind NW at 5 mph, overcast, 38 degrees. Photographs not collected. Nearest water is a temporary wetland 150 meters to the south. Clean facility site with interior and exterior diking and a shallow ditch inside exterior dike for storm water retention. Report indicates spray went into hay field. Hay field is on west, north and east sides. Walked hayfield perimeter but could not locate spray location. No likely impacts to waters.