

Oil Field Environmental Incident Summary

Incident: 20140904082449 **Date/Time of Notice:** 09/04/2014 08:24

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: STATE 16-31

Field Name: CHARLSON

Well File #: 11895

Date Incident: 9/3/2014 **Time Incident:** 13:00

Facility ID Number:

County: MCKENZIE

Twp: 153

Rng: 95

Sec: 16

Qtr: NE NW

Location Description:

Submitted By: Kaylan Dirx

Received By:

Contact Person: Kaylan Dirx
P.O Box 1589
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Popoff

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	9	Barrels	9	Barrels	9	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 10/19/2015

Clean Up Concluded: 9/10/2014

Risk Evaluation:

None- majority of spill was contained on location and the liquids were recovered.

Areal Extent:

Approx. 5-10 gal misted off location to the East covering an area approx. 35' x 10' long.

Potential Environmental Impacts:

None- majority of spill was contained on location and the liquids were recovered.

Action Taken or Planned:

Hydro vac recovered liquids. Waiting on One Call to remove any impacted soil.

Wastes Disposal Location: Liquids were disposed at Clean Energy. Impacted soil will be disposed at Indian Hills.

Agencies Involved:

Updates

Date: 9/4/2014 **Status:** Reviewed - Follow-up Required **Author:** Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to treater popoff, was not contained according to the report. Followup is necessary.

Date: 9/9/2014 **Status:** Inspection **Author:** Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The weather was 43 °F and cloudy, with wind from the northeast at 10 mph. The pad is fenced off; there is a hayfield to the south and east. Walked around the pad edge and did not see any issues. Did not see any oil residue on the pad. No further followup needed at this time.