

Oil Field Environmental Incident Summary

Incident: 20140908220323 **Date/Time of Notice:** 09/08/2014 22:03

Responsible Party: ONEOK Rockies Midstream

Well Operator: ONEOK ROCKIES MIDSTREAM

Well Name: Stockyard Compressor Station

Field Name:

Well File #:

Date Incident: 9/8/2014 **Time Incident:** 07:00

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 99

Sec: 7

Qtr: SW NW

Location Description: 48° 9'41.12"N, 103°28'25.35"W

Submitted By: Kim Rudningen

Received By:

Contact Person: Kim Rudningen
2700 Lincoln Ave SE
Sidney, MT 59270

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: No

Reported to NRC: No

Spilled Units

Recovered Units

Followup Units

Oil

Brine

Other 8 Barrels

Description of Other Released Contaminant:

Natural Gas condensates

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

There are no immediated risks associated with this release.

Areal Extent:

The offsite impact is land north of the facility approximately 50 yards wide and 75 yards long.

Potential Environmental Impacts:

This release was limited to the facility soil surrounding the line that leaked as well as the soil and vegetation on the pasture land immediately adjacent to the leak. There is no impact to surface water nor any subsurface impact.

Action Taken or Planned:

The line was blocked in and blown down. A cleanup crew has begun cleanup work in order to remove all of the contaminated soils surrounding the leak site. The contaminated vegetation will also be removed.

Wastes Disposal Location: contaminated wastes will be disposed of at Secure 13 mile landfill.

Agencies Involved:

Updates

Date: 9/9/2014 **Status:** Inspection

Author: Wax, Pete

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site 17:15, off site 17:45, wind 12 mph NE, 45 degrees, overcast. Condensate pipe ruptured 50 feet inside north fence of yard. Spray traveled outside of fence to the north approximately 300' east and west and 100' north. Hole still open and burst pipe exposed. Primary area of impact already scraped up and left as a dike. URS on site developing details of cleanup plan. Contaminated soil will be removed, area reshaped and seeded.

Date: 9/9/2014 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted the surrounding area. Followup is necessary.