

# Oil Field Environmental Incident Summary

**Incident:** 20141020132702      **Date/Time of Notice:** 10/20/2014 13:27

**Responsible Party:** KODIAK OIL & GAS (USA) INC.

**Well Operator:** KODIAK OIL & GAS (USA) INC.

**Well Name:** ANDERSON 152-103-21-16-1H

**Field Name:** GLASS BLUFF

**Well File #:** 24303

**Date Incident:** 10/16/2014      **Time Incident:** 06:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 152      **Rng:** 103      **Sec:** 21      **Qtr:**

**Location Description:**

**Submitted By:** Britiny Fabry

**Received By:**

**Contact Person:** John Lohman  
1625 BROADWAY STE 250  
DENVER, CO 80202

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Stuffing Box Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** Unknown

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	10	Barrels	10	Barrels	10	barrels
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 7/17/2015

**Clean Up Concluded:** 10/20/2014

**Risk Evaluation:**

none

**Areal Extent:**

**Potential Environmental Impacts:**

Liquid spread on gravel inside of dike

**Action Taken or Planned:**

Vac truck sucked up all liquid in dike. Strata came out and took soil sample and if it tests high in Chlorites, soil will be removed as well. Secondary dikes and liner to be placed directly around Triplex skid

**Wastes Disposal Location:** Liquids put back into production tanks on location. If soil does need to be removed it will be taken to an approved disposal site

**Agencies Involved:**

**Updates**

---

**Date:** 10/27/2014 **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a stuffing box leak, remained on location within the diking according to the report. NDIC retains oversight.