

Oil Field Environmental Incident Summary

Incident: 20141030120815 **Date/Time of Notice:** 10/30/2014 12:08
Responsible Party: WHITING OIL AND GAS CORPORATION
Well Operator: WHITING OIL AND GAS CORPORATION
Well Name: CURL 21-14-2H
Field Name: ELLSWORTH **Well File #:** 26010
Date Incident: 10/30/2014 **Time Incident:** 09:30 **Facility ID Number:**
County: MCKENZIE **Twp:** 149 **Rng:** 100 **Sec:** 14 **Qtr:** NW NE
Location Description: Spill went very slightly south off of facility site onto adjacent field.

Submitted By: Corissa Zimmer **Received By:**
Contact Person: Corissa Zimmer
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Pasture **Affected Medium:** Topsoil

Distance Nearest Occupied Building: 0.4 Mile
Distance Nearest Water Well: 0.4 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No		Reported to NRC: No				
	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels			0	barrels
Brine						
Other						

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 11/12/2014 **Clean Up Concluded:** 11/7/2014

Risk Evaluation:
To be determined.

Areal Extent:
Slightly off of pad onto adjacent field on south side of facility.

Potential Environmental Impacts:

To be determined.

Action Taken or Planned:

Absorbent pads used soak up oil and impacted soil will be removed and hauled to an approved location.

Wastes Disposal Location: Wastes will be disposed in an approved location.

Agencies Involved:

Updates

Date: 10/31/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from a valve/piping leak went partly off location. Followup is necessary.

Date: 11/4/2014 **Status:** Inspection

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

11/4/14 - 13:15 on location. Inspected area where the report indicates that the flow went off location. New erosion control on the outslope appears to conform with the report. No indication of oil staining in the ag field at that location or any other along the south site. Checked soil conductivity in the apparent location. Soil EC was < 1,000 uS/cm. No further inspection needed.