

# Oil Field Environmental Incident Summary

**Incident:** 20141106215245      **Date/Time of Notice:** 11/06/2014 21:52

**Responsible Party:** HUNT OIL COMPANY

**Well Operator:** HUNT OIL COMPANY

**Well Name:** BEAR BUTTE 1-6-7H

**Field Name:** LITTLE TANK

**Well File #:** 24585

**Date Incident:** 11/6/2014      **Time Incident:** 03:08

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 148

**Rng:** 101

**Sec:** 6

**Qtr:**

**Location Description:**

**Submitted By:** Melvin Swenson

**Received By:**

**Contact Person:** Melvin Swenson  
1900 NORTH AKARD STREET  
DALLAS, TX 75201-2300

**General Land Use:** Well/Facility Site

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Stuffing Box Leak

**Release Contained in Dike:** No

**Reported to NRC:** Unknown

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	0.5	Barrels			0.5	barrels
<b>Brine</b>	0.5	Barrels			0.5	barrels

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 4/13/2016

**Clean Up Concluded:** 11/6/2014

**Risk Evaluation:**

Low risk of health, atmosphere and or Explosive dangers

**Areal Extent:**

ground, ditch bank and Cty road 30. Covered roughly 80 yards from the wellhead to the cty road.

**Potential Environmental Impacts:**

there was no standing fluid on the ground leaving location, only a mist from the wind blowing. Will not impact any surface water or groundwater. we will take care of the topsoil that has had a mist sprayed over it.

**Action Taken or Planned:**

Well was shut it immediately  
Contacted JMAC, they will be out tomorrow morning 11-7-14 to start clean up

**Wastes Disposal Location:**

**Agencies Involved:**

**Updates**

---

**Date:** 11/7/2014    **Status:** Inspection

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

11/7/14 - 08:40 on location. Met with company representative and response contractors. Spray from the stuffing box went straight north toward, but not across, road. Personnel were on site shortly after leak began, and the leak was controlled quickly. Lease goes all the way to road ditch (not much of one) and has very recently been reclaimed by the company and seeded. Soil EC by company's probe; background and impact area are very similar at less than 2 mS/cm. Oil spray across the exposed ground is very light. With the recent restoration and seeding, remote location of the site, and low area with no runoff potential, NDDoH decision is to forego any attempt at further restoration. Any tillage and/or amendments would put the recent seeding too deep for good germination. Very light oil impact will naturally attenuate over the winter and early spring.

---

**Date:** 11/7/2014    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill impacted the surrounding location. NDIC retains oversight for the location itself.