

Oil Field Environmental Incident Summary

Incident: 20141215183005 **Date/Time of Notice:** 12/15/2014 18:30

Responsible Party: ONEOK Rockies Midstream

Well Operator:

Well Name:

Field Name:

Well File #:

Date Incident: 12/14/2014 **Time Incident:** 22:41

Facility ID Number:

County: MCKENZIE

Twp: 153 **Rng:** 101 **Sec:** 30 **Qtr:**

Location Description: Southwest of Williston, ND and south of the Missouri River on Hwy. 85. Head West on 45th Street for 2 miles off of 85. The site is on the south side of the road just beyond the green metal gate.

Submitted By: Mitch Anderson

Received By:

Contact Person: Mitch Anderson
2700 Lincoln Avenue SE
Sidney, MT 59270

General Land Use: Badlands Terrain

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine

Other 10 Barrels

Description of Other Released Contaminant:

Natural Gas Liquids (Condensates)

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

There were no immediate health hazards associated with this incident.

Areal Extent:

Approximately 2 acres of topsoil and vegetation were impacted.

Potential Environmental Impacts:

There were no adverse impacts to surface water or groundwater. Vegetation and exposed soil were impacted.

Action Taken or Planned:

The pipeline was capped after the pipeline was blocked in and de-pressurized.

Wastes Disposal Location: Contaminated soils will be likely be hauled to a licensed and approved landfill.

Agencies Involved: McKenzie County Emergency Director

Updates

Date: 12/15/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Notified at approximately 10 a.m. by NDDoH emergency phone. Followed through the morning and early afternoon. Two NDDoH emergency response team members assigned to follow up on 12/16. Photos sent in from county emergency manager and N.D. Game and Fish, as well as a citizen video clip. All in the linked folder. U.S. Army Corps of Engineers, Game and Fish, county emergency manager, local fire department, and sheriff office all responded.

Date: 12/16/2014 **Status:** Inspection

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location at 10:27 A.M. on 12/16/14. Visible impact on snow-covered ground and grass vegetation on the south side of 45th St. Heaviest impact was to an area of approximately 100x50 ft. GPS was used to delineate impacted area. Met with Clean Harbors personnel on site. Plan is to remove impacted vegetation and impacted snow. Cleanup will start as soon as plans are approved. More followup is required.

Date: 5/19/2015 **Status:** Inspection

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 15:30. 59 degrees F, sunny, east wind 10-15 mph. Parked outside of the green fence and walked the area that had been landscaped and excavated. No new vegetative growth was noted in reworked areas. An area south of the road was an open excavation with no pipes exposed; however, the excavation was approximately 150' long by 30' wide and 3' to 5' in depth. Equipment for regrading and reseeding of the area was on location, possibly indicating that more work was yet to be conducted. No visual sign of impacts noted during the inspection. More followup is needed to document revegetation of the area and clarify removal of impacted soils.

Date: 9/3/2015 **Status:** Inspection

Author: Washek, Sandi

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 5:05 pm. 84 degrees F, sunny, SW wind 10 mph. Parked outside of the new brown metal fence and walked the area that had been landscaped and excavated. The area that has been reworked has straw cover and vegetative growth was noted in reworked areas. Will need to inspect next spring to ensure vegetative cover comes back. More follow-up needed.