

Oil Field Environmental Incident Summary

Incident: 20150102092429 **Date/Time of Notice:** 01/02/2015 09:24

Responsible Party: OKEOK ROCKIES MIDSTREAM

Well Operator:

Well Name:

Field Name:

Well File #:

Date Incident: 12/31/2014 **Time Incident:** 15:20

Facility ID Number:

County: WILLIAMS

Twp: 155 **Rng:** 103 **Sec:** 21 **Qtr:** SW

Location Description: Stateline Gas Plant
15071 56th St NW
Williston ND

Submitted By: Kimberly Rudningen

Received By:

Contact Person: Kimberly Rudningen
2700 Lincoln Ave SE
Sidney, Mt 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 300 Feet

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine

Other 30 Gallons

Description of Other Released Contaminant:

The liquid was a mixture of methanol, water, and suspended dirt and rust from pigging and purging a new inlet gas line to the Stateline plant.

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

There were no immediate risks associated with this release.

Areal Extent:

The spill was contained to the facility site.

Potential Environmental Impacts:

There are no impacts to the environment associated with this release as it was cleaned up immediately.

Action Taken or Planned:

The liquids were removed from the ground surface immediately with a vacuum truck. No future action is required.

Wastes Disposal Location: Recovered wastes will be disposed of in a certified disposal location.

Agencies Involved:

Updates

Date: 1/2/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, this spill occurred at a location that is not associated with E & P. Followup is necessary.

Date: 1/6/2015 **Status:** Awaiting Documentation

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

1/6/2015 at 11:53, on location. Met with report contact and facility personnel. Release occurred in pipe fitting when purging line. Spray hit part of piping nearby, but there was no visible impact to snow-covered ground. Bucket placed underneath fitting still contains liquid from release. Personnel will update NDDoH when bucket is emptied.

Date: 1/12/2015 **Status:** Correspondence

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Email received from report contact indicating that bucket has been drained of liquids.

Date: 7/14/2015 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

7/14/2015 at 08:45, on location. Met with report contact. Bucket underneath piping has been removed, no visible impact remaining under piping. No further follow-up required.