

# Oil Field Environmental Incident Summary

**Incident:** 20150313143805      **Date/Time of Notice:** 03/13/2015 14:38  
**Responsible Party:** Kevin Jacob  
**Well Operator:** WHITE OWL ENERGY SERVICES (US) INC.  
**Well Name:** WO WATFORD #1  
**Field Name:** SIVERSTON      **Well File #:** 90172  
**Date Incident:** 3/12/2015      **Time Incident:** 17:30      **Facility ID Number:**  
**County:** MCKENZIE      **Twp:** 150      **Rng:** 98      **Sec:** 22      **Qtr:** NE SW  
**Location Description:** Saltwater Disposal

**Submitted By:** Kevin Jacob      **Received By:**  
**Contact Person:** Kevin Jacob  
P.O. BOX 1983  
DICKINSON, ND 58602

**General Land Use:** Well/Facility Site      **Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1000 Feet  
**Distance Nearest Water Well:** 100 Feet

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** Unknown      **Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	20	Barrels	2	Barrels	20	barrels
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 1/23/2017      **Clean Up Concluded:** 7/23/2015

**Risk Evaluation:**  
unknown

**Areal Extent:**

**Potential Environmental Impacts:**

The pipeline that appears to have failed is six feet below the surface.

**Action Taken or Planned:**

Upon notification, the above named manager, gave direction to shut down the pipeline and isolated it. An emergency one call procedure was enacted. Last night, we started digging with shovels to try to find how deep the leak was. We got down about 3 feet and still could not see the leak. A two man crew arrived on 3/13/15 and determined that we would need a backhoe to get to the depth of 6 feet, due to constraint of a workable area. As of this filing, we are still awaiting this to commence.

**Wastes Disposal Location:** Any water recovered will be sucked up by water tanker and disposed of within our disposal system.

**Agencies Involved:**

**Updates**

---

**Date:** 3/13/2015    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill impacted areas not associated with an E & P location. Followup is necessary.

---

**Date:** 6/25/2015    **Status:** Inspection

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

I went by the site at 12:51 p.m. The weather was clear, 70°F, with the wind west from 5-10 mph. There currently is construction activity on the north and west sides of property. A pad was being constructed on the northwest side. The property drains to two storm water ponds on the south side of property. Could not see any evidence of water leaving property, the oversight of this spill remains with NDIC. No further follow-up needed at this time. 47.79385; - 103.21149