

# Oil Field Environmental Incident Summary

**Incident:** 20150319151812      **Date/Time of Notice:** 03/19/2015 15:18

**Responsible Party:** ENDURO OPERATING, LLC

**Well Operator:** ENDURO OPERATING, LLC

**Well Name:** Gehringer Unit CTB

**Field Name:** MOHALL

**Well File #:**

**Date Incident:** 3/14/2015      **Time Incident:** 07:43

**Facility ID Number:** 403714-02

**County:** BOTTINEAU

**Twp:** 162

**Rng:** 83

**Sec:** 31

**Qtr:** SW NE

**Location Description:**

**Submitted By:** Scott Hunskor

**Received By:**

**Contact Person:** Scott Hunskor  
777 MAIN STREET  
SUITE 800  
FORT WORTH, TX 76102

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	100	Barrels	100	Barrels	100	barrels
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 2/26/2016

**Clean Up Concluded:** 3/16/2015

**Risk Evaluation:**

none

**Areal Extent:**

**Potential Environmental Impacts:**

none

**Action Taken or Planned:**

Opened Valves to equalize tanks, called tanker trucks to load up fluid in dike. Roustabouts in to scrape up affected soil and cover with gravel. An alarm will also be installed on the tank that ran over.

**Wastes Disposal Location:** Fluid hauled to injection wells in the field and soil to PDI

**Agencies Involved:**

**Updates**

---

**Date:** 3/19/2015    **Status:** Reviewed - Assigned to Other Agency    **Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to tank overflow, remained on location within the diking according to the report. NDIC retains oversight.