

Oil Field Environmental Incident Summary

Incident: 20150323081729 **Date/Time of Notice:** 03/23/2015 08:17

Responsible Party: DENBURY ONSHORE, LLC

Well Operator: DENBURY ONSHORE, LLC

Well Name: CHSU CRAIG 31-35 WIP

Field Name: CEDAR HILLS

Well File #:

Date Incident: 3/21/2015 **Time Incident:** 07:00

Facility ID Number:

County: BOWMAN

Twp: 131 **Rng:** 105 **Sec:** 35 **Qtr:** NW NE

Location Description: Majority of release remained on location. Estimated 2 bbls of source water ran north in a 5 foot wide (at the widest) by 150 foot path. No water impacted. Note-Verbally reported to Rick Hutchens NDIC at 3-21-15 4:30 pm

Submitted By: Josh Cuppy

Received By:

Contact Person: Roy Madsen
5320 LEGACY DR
PLANO, TX 75024-3127

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Pump Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	100	Barrels	50	Barrels		

Description of Other Released Contaminant:

Source water

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

2 bbls off location in a narrow path for approximately 150 feet.

Potential Environmental Impacts:

None

Action Taken or Planned:

Recovered standing fluid.

Note-Verbally reported to Rick Hutchens NDIC at 3-21-15 4:30 pm

Wastes Disposal Location:

Agencies Involved: BLM

Updates

Date: 3/23/2015 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Lodgepole source water release off location. Followup is necessary.

Date: 4/7/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 12:41 p.m. The weather was cloudy, 45°F, with the wind from the west at 10-15 mph. The spill ran off the pad on the north side. This area of the ditch has been diked up north of the power box. A culvert runs north to south at the base of the pad. Samples were taken. More followup needed. 46.13142, -103.77097

Date: 4/21/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 12:18 p.m. The weather was clear, 43 °F, with the wind from the north 10-15 mph. The area on the north side of pad looks the same. More followup needed.

Date: 6/9/2015 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

6/9/2015 at 16:16, on location. North side of wellpad has been graded. Some vegetation having difficulty reestablishing due to very sandy soil in spots, however rest of area has vegetation starting to grow.

Date: 10/8/2015 **Status:** Correspondence

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

NDDoH test results show all chloride concentrations are below department action levels.