

Oil Field Environmental Incident Summary

Incident: 20150415151637 **Date/Time of Notice:** 04/15/2015 15:16

Responsible Party: PETRO-HUNT, L.L.C.

Well Operator: PETRO-HUNT, L.L.C.

Well Name: SILURIAN 54-1

Field Name: CHARLSON

Well File #: 12031

Date Incident: 4/15/2015 **Time Incident:** 08:00

Facility ID Number:

County: MCKENZIE

Twp: 153

Rng: 95

Sec: 9

Qtr:

Location Description: Along roadway just south of Silurian 54-1, SWSW Sec. 9 T153N R95W

Submitted By: Shawn Reisenauer

Received By:

Contact Person: Shawn Reisenauer
390 119th Ave. SW
Killdeer, ND 58640

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	50	Barrels			50	barrels

Description of Other Released Contaminant:

Freshwater

Inspected:

Written Report Received: 1/6/2016

Clean Up Concluded: 4/17/2015

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Line was shut in. In process of digging up and repairing line.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 4/15/2015 **Status:** Reviewed - Follow-up Required

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to pipeline leak, got off location. Followup is necessary.

Date: 4/23/2015 **Status:** Correspondence

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Request copy of sample results.

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 12:40 p.m. The weather is cloudy, 47 °F, with the wind from the southeast 10-15 mph. I talked to rep from the company; he indicated that this is a fresh water line. A new water sample was taken from the well to verify it is fresh water. The break occurred just north of the cattle crossing on the west side of road. The cattle crossing is located toward the south side of quarter, south side of section . The break has been repaired and area reclaimed. I will request the sample results. 48.08452; - 102.91238