

# Oil Field Environmental Incident Summary

**Incident:** 20150513090955      **Date/Time of Notice:** 05/13/2015 09:09

**Responsible Party:** HESS CORPORATION

**Well Operator:** HESS CORPORATION

**Well Name:** CMU Satellite 6

**Field Name:** CAPA

**Well File #:**

**Date Incident:** 5/12/2015      **Time Incident:** 08:30      **Facility ID Number:** 400486-02

**County:** WILLIAMS      **Twp:** 155      **Rng:** 95      **Sec:** 20      **Qtr:** NE NW

**Location Description:**

**Submitted By:** Alex Beach

**Received By:**

**Contact Person:** Jason Henry  
3015 16TH ST SW STE 20  
MINOT, ND 58701

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1.3 Mile

**Distance Nearest Water Well:** 1.3 Mile

**Type of Incident:** Pump Leak

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	35	Barrels			35	barrels
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 1/13/2016

**Clean Up Concluded:** 5/22/2015

**Risk Evaluation:**

There is no immediate risk suspected at this time.

**Areal Extent:**

**Potential Environmental Impacts:**

The 35 bbl. release impacted an estimated 45' by 63' area of Well/Facility soil. All of the released fluid remained on location. There are no additional environmental impacts suspected.

**Action Taken or Planned:**

A vacuum truck was on location for different job, and was able to begin cleanup operations immediately.

**Wastes Disposal Location:** The impacted material will be taken to an approved waste disposal facility.

**Agencies Involved:**

**Updates**

---

**Date:** 5/13/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a pump leak, remained on location according to the report. NDIC retains oversight.