

Oil Field Environmental Incident Summary

Incident: 20150520104915 **Date/Time of Notice:** 05/20/2015 10:49

Responsible Party: PETRO-HUNT, L.L.C.

Well Operator: PETRO-HUNT, L.L.C.

Well Name: SABROSKY 4-31-4C

Field Name: LITTLE KNIFE

Well File #: 6210

Date Incident: 5/19/2015 **Time Incident:** 15:00

Facility ID Number:

County: DUNN

Twp: 145

Rng: 97

Sec: 31

Qtr:

Location Description: Spill is located on pipeline ROW on the west side of the road between the Sabrosky 4-31-4C and CTB #2

Submitted By: Shawn Reisenauer

Received By:

Contact Person: Shawn Reisenauer
390 119th Ave. SW
Killdeer, ND 58640

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	2	Barrels	2	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 5/26/2015

Clean Up Concluded: 5/20/2015

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Line was shut in and contaminated soil is being dug up and replaced with clean material.

Wastes Disposal Location: Contaminants will be hauled to Chimney Butte Disposal.

Agencies Involved:

Updates

Date: 5/20/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill occurred along a pipeline right of way. Followup is necessary to ensure proper remediation.

Date: 7/21/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 16:52. The weather was sunny, 83°F, with the wind from the southeast 10-15 mph. An area just west of the well on the west side of lease road has been disturbed. This area has been redone and seeded. The grass is starting to come back. More follow-up is needed to check on vegetative growth.