

Oil Field Environmental Incident Summary

Incident: 20150522151729 **Date/Time of Notice:** 05/22/2015 15:17

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: GO-PERDUE- 157-97-0112H-2

Field Name: RAY

Well File #: 28992

Date Incident: 5/21/2015 **Time Incident:** 20:00

Facility ID Number:

County: WILLIAMS

Twp: 157 **Rng:** 97 **Sec:** 1 **Qtr:**

Location Description:

Submitted By: Jason Henry

Received By:

Contact Person: Jason Henry
3015 16th Street SW, Suite 20
Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.6 Mile

Distance Nearest Water Well: 0.6 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	22.5	Barrels			22.54	barrels

Description of Other Released Contaminant:

Approximately 22.5 bbls of fresh water was released from a pump due to a hose failure during frac operations.

Inspected:

Written Report Received: 1/13/2016

Clean Up Concluded: 5/30/2015

Risk Evaluation:

The source of the fresh water release was secured immediately upon discovery.

Areal Extent:

N/A - the release remained on the location.

Potential Environmental Impacts:

Due to the nature of this release (approximately 22.5 bbls of fresh water and approximately 0.02 bbls of DWP 621 Friction Reducer), there are no anticipated impacts to be addressed.

Action Taken or Planned:

The soil that was affected by the release of fresh water and DWP 621 Friction Reducer will be excavated and transported off-site for proper disposal.

Wastes Disposal Location: At a properly permitted disposal facility.

Agencies Involved:

Updates

Date: 5/26/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.