

Oil Field Environmental Incident Summary

Incident: 20150605154213 **Date/Time of Notice:** 06/05/2015 15:42

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: WALLACE 7-1H

Field Name: MURPHY CREEK

Well File #: 20453

Date Incident: 6/4/2015 **Time Incident:** 14:30

Facility ID Number:

County: DUNN

Twp: 143

Rng: 94

Sec: 7

Qtr:

Location Description:

Submitted By: Alex Beach

Received By:

Contact Person: Jason Henry
3015 16th Street SW, Suite 20
Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 450 Feet

Distance Nearest Water Well: 450 Feet

Type of Incident: Tank Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.8	Barrels			0	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/13/2016

Clean Up Concluded: 7/1/2015

Risk Evaluation:

There is no immediate risk to report at this time

Areal Extent:

Potential Environmental Impacts:

The estimated 0.8 bbl release impacted an approximate 4' by 20' area of well/facility soil with a smaller amount leaving the location and migrating into a farmer's field. At this time there are no additional potential environmental impacts to report.

Action Taken or Planned:

Contractors and Hess personnel used absorbent pads to soak up the oil that had pooled. Clean-up operations will begin on the Hess site as soon as possible. The Land Department was notified and the off-site clean-up will be coordinated with landowner.

Wastes Disposal Location: The waste will be taken to an approved waste disposal facility.

Agencies Involved:

Updates

Date: 6/5/2015 **Status:** Reviewed - Follow-up Required **Author:** Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted areas off location. Followup is required.

Date: 7/20/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 14:36. The weather was sunny, 75°F, with the wind from the northwest 10-15 mph. There is an area that has been disturbed on the north side of dike system going down the pad side into a small area of the field. The area has some erosion due to recent rain into the field. It does not appear the pad side has been seeded. More follow-up needed to check on vegetation growth.
47.21324 -102.63537

Date: 8/31/2016 **Status:** Inspection

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 8/31/2016, at 12:36 p.m. Vegetation to the north is green and growing. There is a small area in the sunflower field (approximately 20 X 20 feet) that is bare, but this may be due to natural runoff. Conductivity readings in bare area are consistent with background levels in area. Follow up during next growing season.