

Oil Field Environmental Incident Summary

Incident: 20150626121600 **Date/Time of Notice:** 06/26/2015 12:16

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: P THOMAS 154-98-15W-33-28-2H

Field Name: TRUAX

Well File #: 28909

Date Incident: 6/20/2015 **Time Incident:** 12:00

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 98

Sec: 33

Qtr:

Location Description:

Submitted By: Corissa Zimmer

Received By:

Contact Person: Corissa Zimmer
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	Barrels			0.5	barrels
Brine	0.5	Barrels			0.5	barrels

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/11/2016

Clean Up Concluded: 6/22/2015

Risk Evaluation:

None noted.

Areal Extent:

Potential Environmental Impacts:

None noted.

Action Taken or Planned:

Spill was cleaned, and in the future there will be increased maintenance and awareness about this potential issue.

Wastes Disposal Location: Wastes will be disposed of in an approved facility.

Agencies Involved:

Updates

Date: 6/29/2015 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, did not remain within diking. More follow-up needed.

Date: 7/1/2015 **Status:** Correspondence

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received an email from the company contact showing three photos of the release area. Photos were not close enough to determine if proper cleanup had been made. Further follow-up needed. Email and photos added to folder.

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 10:57 a.m. Weather was sunny with wind out of the west at 20 mph and a temperature of 34 degrees F. Walked the berm surrounding the oil pad along the west, north and south sides. No visible staining of soil found, and vegetation on the berm was good in many spots but sparse in a few. This could be due to the gravelly soil located in those areas or due to reseeding of the area. Have company provide soil sample of berm in impact area. Follow-up needed if lab result comes back elevated.