

Oil Field Environmental Incident Summary

Incident: 20150706142628 **Date/Time of Notice:** 07/06/2015 14:26
Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Name: CCU WILLIAM 34-20TFH
Field Name: CORRAL CREEK **Well File #:** 25280
Date Incident: 7/6/2015 **Time Incident:** 10:00 **Facility ID Number:**
County: DUNN **Twp:** 147 **Rng:** 95 **Sec:** 29 **Qtr:** NW NE
Location Description: Immediately adjacent to the south side of the well pad.

Submitted By: Lewis Schoenberger **Received By:**
Contact Person: Lewis Schoenberger
PO BOX 51810
MIDLAND, TX 79710-1810

General Land Use: Pasture **Affected Medium:** Topsoil

Distance Nearest Occupied Building: 1 Mile
Distance Nearest Water Well: 1 Mile

Type of Incident: Equipment Failure

Release Contained in Dike: No **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	6	Barrels				
Brine	2	Barrels				
Other						

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 8/3/2016 **Clean Up Concluded:** 7/15/2015

Risk Evaluation:
None

Areal Extent:
Approximately 100 feet by 50 feet immediately south of the well pad.

Potential Environmental Impacts:

None

Action Taken or Planned:

A vacuum truck has been dispatched to collect free liquids. Oil impacted gravel from the well pad as well as oil impacted soil and vegetation from the area off of the pad will be collected for appropriate disposal.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 7/6/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary this spill impacted the surrounding area. Follow-up is necessary.

Date: 7/14/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site 16:31. The weather was sunny, 86°F, with the wind from the northwest 5-10 mph. I talked to the person who was listed as the contact on the spill report. He indicated that the spill was on the tank battery site which is located just north of the wells. The area was cleaned up last Friday. The spill appears to have flowed off the pad on the east side under the cattle crossing and down the lease road ditch. This area has been cleaned and erosion controls are in place down to culvert. I could not see any impacted vegetation near the culvert or on the east side of lease road. The company was asked to collect confirmation samples and submit the results to the Department. More follow-up is needed to check on vegetative growth.