

Oil Field Environmental Incident Summary

Incident: 20150714223812 **Date/Time of Notice:** 07/14/2015 22:38

Responsible Party: Polar Midstream, LLC

Well Operator:

Well Name: Bibler Lateral North Trunk

Field Name:

Well File #:

Date Incident: 7/14/2015 **Time Incident:** 08:00

Facility ID Number:

County: WILLIAMS

Twp: 155 **Rng:** 99 **Sec:** 16 **Qtr:** NE NE

Location Description: The line strike occurred on the Bibler Lateral North Trunk pipeline near the Whiting Mildred 94-01H well pad. The produced water pipeline is owned and operated by Polar Midstream, LLC. The coordinates of the incident are 48.2539, -103.4189.

Submitted By: Tarik Ibrahim

Received By:

Contact Person: Tarik Ibrahim
5831 123rd Drive NW
Epping, ND 58843

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	2.1	Barrels	2.1	Barrels		
Other						

Description of Other Released Contaminant:

N/A

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No impact to surface waters.

Areal Extent:

The spill was contained on the right of way in a bell hole dug by Spydr Oil Field Services.

Potential Environmental Impacts:

The spill impacted the soil inside the bell hole. The impacted soil will be excavated and removed from the location by Spydr Oil Field Services. There was no impact or potential impact to any surface waters.

Action Taken or Planned:

The segment of the Bibler Lateral North Trunk pipeline was shut in and locked out by Polar Midstream, LLC personnel. The pipeline segment will be repaired prior to being put back in service. Spydr Oil Field Services has taken responsibility for remediating the impacted soil, and for disposing of any waste associated with this incident.

Wastes Disposal Location: Spydr Oil Field Services has taken responsibility for the disposing of the impacted soil and produced water at a licensed facility.

Agencies Involved:

Updates

Date: 7/15/2015 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to incident report, release impacted areas off location. Follow-up is required.

Date: 7/31/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 16:17 7/29/2015. No sign of spill at the time of inspection. No follow-up is necessary.