

Oil Field Environmental Incident Summary

Incident: 20150809155305 **Date/Time of Notice:** 08/09/2015 15:53

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: LANDBLOM 1-35H

Field Name: STONEVIEW

Well File #: 17286

Date Incident: 8/9/2015 **Time Incident:** 05:30

Facility ID Number:

County: DIVIDE

Twp: 160

Rng: 95

Sec: 35

Qtr:

Location Description:

Submitted By: Todd Senescall

Received By:

Contact Person: Lane Titus
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

| | Spilled | Units | Recovered | Units | Followup | Units |
|--------------|----------------|--------------|------------------|--------------|-----------------|--------------|
| Oil | 2 | Barrels | 2 | Barrels | 2 | barrels |
| Brine | 1 | Barrels | 1 | Barrels | 1 | barrels |

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 8/17/2015

Clean Up Concluded: 8/9/2015

Risk Evaluation:

fire

Areal Extent:

Potential Environmental Impacts:

location soil

Action Taken or Planned:

well shut in and stuffing box rubber replaced. Standing fluid sucked up. Contaminated soil removed. Scoria lightly misted was dragged.

Wastes Disposal Location: liquid - SWD
Soil - PDI

Agencies Involved: John Rumppe - NDIC Inspector

Updates

Date: 8/10/2015 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a stuffing box leak, remained on the well/facility site according to the report. NDIC retains oversight.