

# Oil Field Environmental Incident Summary

**Incident:** 20150820105848      **Date/Time of Notice:** 08/20/2015 10:58

**Responsible Party:** CONTINENTAL RESOURCES, INC.

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** WALTER 11-1SH

**Field Name:** CEDAR HILLS

**Well File #:** 17131

**Date Incident:** 8/17/2015      **Time Incident:** 08:00

**Facility ID Number:**

**County:** BOWMAN

**Twp:** 130

**Rng:** 106

**Sec:** 1

**Qtr:**

**Location Description:** Pasture/borrow ditch along lease road

**Submitted By:** Patrick Skillestad

**Received By:**

**Contact Person:** Patrick Skillestad  
PO BOX 268870  
OKLAHOMA CITY, OK 73126

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	10	Gallons	10	Gallons	10	gallons
<b>Brine</b>	10	Gallons	10	Gallons	10	gallons

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 9/14/2015

**Clean Up Concluded:** 8/20/2015

**Risk Evaluation:**

None

**Areal Extent:**

4 ft x 4 ft area in borrow ditch.

**Potential Environmental Impacts:**

Topsoil in pasture.

**Action Taken or Planned:**

Line was exposed and repaired. Matt Tibor with NDIC was notified of the incident on Aug 17 at 1:37 pm. This on-line report is being submitted beyond the 24 hour window due to the fact that there were multiple flow lines in the area and the specific flow line and cause of the leak could not be immediately identified. More specifically, One-Call locates and isolating flow lines to determine which well the leaking flow line was connected delayed reporting efforts.

**Wastes Disposal Location:** Little Missouri Special

**Agencies Involved:**

**Updates**

---

**Date:** 8/20/2015    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill impacted the surrounding area. Followup is necessary.

---

**Date:** 8/26/2015    **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

8/26/2015 at 19:57, on location. Area of pasture in borrow ditch for lease road is about 4,000 feet northwest of the well location. Lease road serves multiple wells in the area. Approximate location is in the NW 1/4 of the SE 1/4, Section 35, T131N, R106W. It has been scraped up, and there is no visible staining on vegetation outside of scraped area. A couple of dirt clods had some staining, but that should naturally attenuate. No further followup required.

---

**Date:** 3/10/2016    **Status:** Correspondence

**Author:** Suess, Bill

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Bill Suess sent a No Further Action letter dated March 10, 2016.