

Oil Field Environmental Incident Summary

Incident: 20150826091319 **Date/Time of Notice:** 08/26/2015 09:13

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: BL-ODEGAARD- 156-95-2116H-7

Field Name: BEAVER LODGE

Well File #: 30673

Date Incident: 8/25/2015 **Time Incident:** 15:00

Facility ID Number:

County: WILLIAMS

Twp: 156

Rng: 95

Sec: 21

Qtr: SW SW

Location Description: Dry grass in-between the well site and cultivated wheat field.

Submitted By: Alex Beach

Received By:

Contact Person: Jason Henry
1501 MCKINNEY
HOUSTON, TX 77010

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.8 Mile

Distance Nearest Water Well: 0.8 Mile

Type of Incident: Fire

Release Contained in Dike: No

Reported to NRC: No

Spilled Units

Recovered Units

Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

Flame from flare

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

There are no immediate risks at this time.

Areal Extent:

15' by 30'

Potential Environmental Impacts:

There are no potential environmental impacts to report at this time.

Action Taken or Planned:

When the fire was spotted, the well was shut in. The fire was extinguished. A fire-watch was assigned to that area.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 8/26/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary to ensure there are not lasting impacts.

Date: 9/10/2015 **Status:** Inspection

Author: Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On-site at 4:20 pm. Weather is 61 degrees F, sunny, wind 8mph NE. No burned grass or oil/brine seen.

On the East side of well pad and continuing to the east onto the ground off-site, is an apparent area of erosion. This area runs for 20-30+ feet down the hill into the grass. Contacting company rep to inform.