

Oil Field Environmental Incident Summary

Incident: 20151006210406 **Date/Time of Notice:** 10/06/2015 21:04

Responsible Party: ARSENAL ENERGY USA INC.

Well Operator: ARSENAL ENERGY USA INC.

Well Name: BRENLEE 100-19H

Field Name: STANLEY

Well File #: 19106

Date Incident: 10/6/2015 **Time Incident:** 10:30

Facility ID Number:

County: MOUNTRAIL

Twp: 155 **Rng:** 90 **Sec:** 19 **Qtr:**

Location Description: South of Stanley on Hiway 8 to 56th Street, Go East 2.75 miles, Location on North side of road.

Submitted By: Gary Ramsdell

Received By:

Contact Person: Gary Ramsdell
STE. 1900, 639 5TH AVE. SW
CALGARY, AB T2P 0M9

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 2500 Feet

Distance Nearest Water Well: 400 Feet

Type of Incident: Treater Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil		barrels			59	barrels
Brine		barrels			5	barrels
Other						

Description of Other Released Contaminant:

.

Inspected:

Written Report Received: 12/1/2015

Clean Up Concluded: 10/7/2015

Risk Evaluation:

Little to none.

Areal Extent:

Misting of oil on equipment and mist of oil that carried into pasture affecting 2000-3000 sq ft

Potential Environmental Impacts:

Slight impact to vegetation in pasture.

Action Taken or Planned:

Well and equipment shut in, Equipment washed off and liquids sucked up and put into tank onsite.

Wastes Disposal Location: Soil and other affected material will be hauled to landfill.

Agencies Involved: NDIC Jason Hicks

Updates

Date: 10/7/2015 **Status:** Reviewed - Follow-up Required

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to treater leak, got off location. Followup is necessary.

Date: 10/13/2015 **Status:** Inspection

Author: Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site at 5:15 p.m. Sunny, 63 degrees, wind 18 mph NW. Walked perimeter on all sides and across the road to the south. No visual evidence of impact seen.