

Oil Field Environmental Incident Summary

Incident: 20151102155508 **Date/Time of Notice:** 11/02/2015 15:55

Responsible Party: OASIS PETROLEUM NORTH AMERICA LLC

Well Operator: OASIS PETROLEUM NORTH AMERICA LLC

Well Name: HERBERT 5602 43-9H

Field Name: BULL BUTTE

Well File #: 20787

Date Incident: 11/2/2015 **Time Incident:** 14:00

Facility ID Number:

County: WILLIAMS

Twp: 156 **Rng:** 102 **Sec:** 9 **Qtr:** SW SE

Location Description:

Submitted By: Luke Radke

Received By:

Contact Person: Luke Radke
1001 FANNIN STE 1500
HOUSTON, TX 77002

General Land Use: Badlands Terrain

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil					10	gallons

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 2/19/2016

Clean Up Concluded: 11/28/2015

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Mow and bag clippings

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 11/2/2015 **Status:** Correspondence

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Requested clarification on the amount spilled at the Herbert 43-9H.

According to the company representative, the mist sprayed out about 20 feet from the wellpad and only a few gallons impacted areas off of location.

Followup is necessary.

Date: 11/2/2015 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to incident report, release impacted area off location. Followup is required.

Date: 12/3/2015 **Status:** No Further Action Requested

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

This pad has two pumps that are not labeled. Walked around the perimeter and observed one oil-stained tumbleweed on east side of pad. No further impacts observed along the east side of pad beyond barb wire fence. No further action required at this time.