

Oil Field Environmental Incident Summary

Incident: 20151112110118 **Date/Time of Notice:** 11/12/2015 11:01

Responsible Party: Hiland Partners

Well Operator:

Well Name:

Field Name:

Well File #:

Date Incident: 11/12/2015 **Time Incident:** 05:45

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 102

Sec: 6

Qtr:

Location Description: 3507 149 Ave. NW - Alexander, ND 58831
Watford City Gas Plant

Submitted By: John Greer

Received By:

Contact Person: John Greer
1001 Louisiana, Suite 1000
Houston, TX 77002

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Truck Overflow

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	3	Barrels	1	Barrels		

Description of Other Released Contaminant:

Atmospheric Condensate at Gas Plant from gathering field prior to leaving gas plant.

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Minimal risk

Areal Extent:

Contained on the plant site loading area. Approx 30'x20' = irregular shape. No offsite impact

Potential Environmental Impacts:

Minimal impacts.

Action Taken or Planned:

Truck loading was stopped. Free liquids were recovered. Impacted soil is being scraped and placed in lined containment area awaiting sampling and soil disposal.

Wastes Disposal Location: To be determined. Likely approved Landfill or Thermal Destruction facility.

Agencies Involved:

Updates

Date: 11/12/2015 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a truck overflow, occurred at a gas plant not permitted by NDIC. Further followup needed.

Date: 12/2/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site 10:15 a.m. The weather was sunny, 23°F, with wind from the southwest 5-10 mph. I met with personnel at the site. They took me to the area of the spill; there was a truck loading. The product was lost through a valve that is left open to allow venting. The condensate went onto the road behind the truck next to the loading area. The road has been cleaned up. No further followup at this time. 47.92176,-103.77924

Date: 12/7/2015 **Status:** Correspondence

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Manager of plant requested information about who reported spill.