

# Oil Field Environmental Incident Summary

**Incident:** 20160113152526      **Date/Time of Notice:** 01/13/2016 15:25

**Responsible Party:** HESS BAKKEN INVESTMENTS II, LLC

**Well Operator:** HESS BAKKEN INVESTMENTS II, LLC

**Well Name:** EN-L CVANCARA- 155-93-2627H-11

**Field Name:** ROBINSON LAKE

**Well File #:** 30667

**Date Incident:** 1/13/2016      **Time Incident:** 07:30

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 155

**Rng:** 93

**Sec:** 26

**Qtr:**

## Location Description:

**Submitted By:** Alberto Yates

**Received By:**

**Contact Person:** Troy Brunsell  
1501 MCKINNEY  
HOUSTON, TX 77010

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.5 Mile

**Distance Nearest Water Well:** 0.5 Mile

**Type of Incident:** Fire

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>					0	barrels
<b>Brine</b>					0	barrels
<b>Other</b>					0	barrels

## Description of Other Released Contaminant:

LEL Gas from wellhead

**Inspected:**

**Written Report Received:** 1/28/2016

**Clean Up Concluded:** 1/25/2016

## Risk Evaluation:

There is no immediate risk to report at this time.

## Areal Extent:

No offsite impacts.

**Potential Environmental Impacts:**

There are no potential environmental impacts to report at this time.

**Action Taken or Planned:**

Flash Fire was contained and extinguished on its own.  
There was not a specific preventative action plan developed as a result of this incident.

**Wastes Disposal Location:** No waste generated for disposal.

**Agencies Involved:**

**Updates**

---

**Date:** 1/13/2016    **Status:** Reviewed - Assigned to Other Agency    **Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, lower explosive limit (LEL) gas was released from the well pad and remained on constructed well site. NDIC retains oversight.