

Oil Field Environmental Incident Summary

Incident: 20160204115236 **Date/Time of Notice:** 02/04/2016 11:52

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: P EARL RENNERFELDT 154-99-2-3-27-2H

Field Name: EPPING

Well File #: 30839

Date Incident: 2/4/2016 **Time Incident:** 08:30

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 99

Sec: 3

Qtr:

Location Description: an area approximately 100 yds by 30 yds to the NE of the facility.

Submitted By: Daniel Ryan

Received By:

Contact Person: Daniel Ryan
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	Barrels			0.5	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/4/2016

Clean Up Concluded: 2/20/2016

Risk Evaluation:

None noted.

Areal Extent:

an area approximately 100 yds by 30 yds to the NE of the facility.

Potential Environmental Impacts:

To be determined.

Action Taken or Planned:

Impacted material in process of being cleaned. Mowers are out and impacted snow being scooped up.

Wastes Disposal Location: An approved location.

Agencies Involved:

Updates

Date: 2/4/2016 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release was not contained to the well pad. Further follow-up necessary.

Date: 2/12/2016 **Status:** Inspection

Author: Kannenberg, Derek

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Date: 02/11/2016. Time: 1000. Observers: Kathleen Kangas, Derek Kannenberg. 18 degrees F, snowing, wind 7 mph east. Approximatley 0.5 barrel of mist drifted off the NE corner of the well pad, and drifted across the road and into adjacent field. Excavated impacted snow and planned to follow up with mowing and disposing of impacted vegetation. Snow cover made confirmation difficult. Follow-up required to ensure mowing and disposal are completed.

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received email from company contact with pictures and test results.

According to the information provided, there is no need for additional follow-up. The area appears to have been properly cleaned up when samples were taken.

No follow-up is necessary.