

Oil Field Environmental Incident Summary

Incident: 20160408100057 **Date/Time of Notice:** 04/08/2016 10:00

Responsible Party: LIME ROCK RESOURCES III-A, L.P.

Well Operator: LIME ROCK RESOURCES III-A, L.P.

Well Name: EDWARD POLENSKY 1-13-24H-142-97

Field Name: WILLMEN

Well File #: 20349

Date Incident: 4/7/2016

Time Incident: 09:30

Facility ID Number:

County: DUNN

Twp: 142

Rng: 97

Sec: 12

Qtr:

Location Description:

Submitted By: Robyn Espinoza

Received By:

Contact Person: Robyn Espinoza
1111 BAGBY, SUITE 4600
HOUSTON, TX 77002

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	27	Barrels	6	Barrels	6	barrels
Brine	3	Barrels				
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 7/20/2016

Clean Up Concluded: 5/20/2016

Risk Evaluation:

Contaminated surface materials

Areal Extent:

Adjacent land east of the treaters have a light mist on the vegetation

Potential Environmental Impacts:

Contaminated surface materials

Action Taken or Planned:

The well was shut in to prevent further release, a vac truck was dispatched to recover all standing liquids. SM Fencing was immediately dispatched to begin cutting and bagging all affected vegetation and straw wattles were placed at the base of the impacted vegetation to collect any runoff in the event we get precipitation.

Wastes Disposal Location: Chimney Butte

Agencies Involved: North Dakota Department of Health

Updates

Date: 4/8/2016 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted areas off location. Follow-up is required.

Date: 4/13/2016 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site 9:29 a.m. The weather was sunny, 52°F, wind from the south 5-10 mph. The spill occurred on the east side of pad and into a pasture. The area is on a hill side, and there are no drainages near the site. The cleanup crew is working at the site. They have mowed an area of 400 yards X 100 yards down to a brush area on east side of pasture. The pasture area next to the pad has soil removed. Personnel for the clean-up crew indicated that the impacted area will be fenced off; erosion controls will be placed on the bare soil area. Samples are being taken in the next couple of days. More follow-up needed. 47.12638,-102.97101

Date: 5/17/2016 **Status:** Inspection

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 5/17/2016, at 12:35 p.m. Impacted area off location is to the east of treater onto a side hill that slopes to the south and east. Vegetation has been mowed. Conductivity probe showed area to the east has elevated conductivity readings. I spoke to company contact, and they are aware of this. One Call was at location marking lines, and more excavation will take place in the next couple of days. Samples will be collected after further work is done at location. Further follow-up is required.

Date: 8/17/2016 **Status:** Inspection

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 1220 MT. Erosion control has been placed in area of release. The grass has started to come back, although it is patchy in some areas. Further follow-up needed on vegetation regrowth.