

Oil Field Environmental Incident Summary

Incident: 20160711153010 **Date/Time of Notice:** 07/11/2016 15:30

Responsible Party: EMERALD OIL, INC

Well Operator: EMERALD OIL, INC

Well Name: BILLY RAY VALENTINE 1-8-5H

Field Name: BOXCAR BUTTE

Well File #: 27979

Date Incident: 7/10/2016 **Time Incident:** 07:00

Facility ID Number:

County: MCKENZIE

Twp: 148 **Rng:** 102 **Sec:** 8 **Qtr:**

Location Description: Location: SESW 8-148-102 Footages: 325 FSL 1450 FWL Latitude: 47.648197 Longitude: -103.709511

Submitted By: Rachael Overbey

Received By:

Contact Person: Ian Myers
200 COLUMBINE ST, STE 500
DENVER, CO 80206

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Barrels	5	Barrels	5	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 12/21/2016

Clean Up Concluded: 7/10/2016

Risk Evaluation:

None

Areal Extent:

90x20'

Potential Environmental Impacts:

There is no running water near location; no contamination of ground or surface water. Only top soil and plant life would be exposed.

Action Taken or Planned:

Clean up is complete; all fluid was sucked up and contaminated soil will be hauled off and replaced with new class 5 as needed

Wastes Disposal Location: IHD

Agencies Involved:

Updates

Date: 7/11/2016 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release was not contained to the well pad. Further follow-up needed.

Date: 8/3/2016 **Status:** Inspection

Author: Washek, Sandi

Updated Oil Volume: 5.00 barrels

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 10:55 a.m. Weather was sunny, 74 degrees F, wind out of the SW at 15 mph. Walked the site. No staining of soil or vegetation was observed. Only water on site was a small water puddle with no sheen on it, and it tested less than 31 parts per million (ppm) for chlorides.