

Oil Field Environmental Incident Summary

Incident: 20160722101807 **Date/Time of Notice:** 07/22/2016 10:18

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: BLSU Line Heater #3 155-95-06

Field Name: BEAVER LODGE

Well File #:

Date Incident: 7/21/2016 **Time Incident:** 15:00

Facility ID Number:

County: WILLIAMS

Twp: 155 **Rng:** 95 **Sec:** 6 **Qtr:**

Location Description: BLSU Line Heater #3 is located at the corner of 105th Ave. NW and 59th St. NW (Lat,48.270261 Long, 102.951092).

Submitted By: Alberto Yates

Received By:

Contact Person: Troy Brunsell
3015 16TH ST SW STE 20
MINOT, ND 58701

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building: 2877 Feet

Distance Nearest Water Well: 2877 Feet

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	3	Gallons				

Description of Other Released Contaminant:

Emulsion - mixture of water and oil approx. 3 gallons covering a 15ft X 18ft area.

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

There is no immediate risk to report

Areal Extent:

Approx. 3 gals of Emulsion was released impacting a 15ft X 18ft area to the south of the Line heater

Potential Environmental Impacts:

The 3 gallons of emulsion released impacted the ground. NO SENSITIVE AREA IMPACTS.

Action Taken or Planned:

Hammer union was re-installed and isolated the line. Arrangements were made for the impacted material to be cleaned up and disposed of to an approved waste facility.

Wastes Disposal Location: The recovered waste will be taken to an approved waste disposal facility.

Agencies Involved:

Updates

Date: 7/22/2016 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted areas off location. Follow-up is required.

Date: 7/26/2016 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

7/26/2016 at 15:20, on location. Heater is a bit due east of the intersection listed in the description. The only thing right at the corner is a cemetery. Heater is near some pig launchers and other piping on the north side of 59th St NW. Heater is currently disassembled, and there is scattered staining around base of unit. There is plastic tarp underneath the oil tubes from the heater to catch any oil from the tubes. Recommend follow-up once heater is reassembled and area near heater is given a final cleanup to catch any leaks during reassembly.