

# Oil Field Environmental Incident Summary

**Incident:** 20160724100303      **Date/Time of Notice:** 07/24/2016 10:03

**Responsible Party:** HRC OPERATING, LLC

**Well Operator:** HRC OPERATING, LLC

**Well Name:** MILLER 157-101-12D-1-2H

**Field Name:** OTTER

**Well File #:** 26342

**Date Incident:** 7/22/2016      **Time Incident:** 10:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 157      **Rng:** 101      **Sec:** 12      **Qtr:**

## Location Description:

**Submitted By:** Chris Martinez

**Received By:**

**Contact Person:** Chris Martinez  
1801 CALIFORNIA STREET  
SUITE 3500  
DENVER, CO 80202

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	1	Barrels	1	Barrels	1	barrels
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 1/23/2017

**Clean Up Concluded:** 7/22/2016

**Risk Evaluation:**

No immediate risk to personnel or the environment

**Areal Extent:**

contained within dike

**Potential Environmental Impacts:**

No potential environmental impacts

**Action Taken or Planned:**

Production line closed, tank emptied, called for repairs

**Wastes Disposal Location:**

**Agencies Involved:**

**Updates**

---

**Date:** 7/25/2016    **Status:** Reviewed - Assigned to Other Agency

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a valve/piping connection leak, remained within the facility diking. NDIC retains oversight.