

# General Environmental Incident Summary

**Incident:** 3227      **Date/Time Notice:** 3/5/2014      0635      **DEM Incident No:**  
**Responsible Party:** RockPile Energy  
**Date Incident:** 3/5/2014      **Time Incident:** 0630      **Duration:** 2 minutes  
**County:** Stark      **Twp:** 139      **Rng:** 99      **Sec:** 10      **Qtr:**  
**Lat:** 46.86248      **Long:** -103.15570      **Method:** Interpolation from map  
**Location Description:** Whiting - Kanrmas Federal 14-10PH  
S on 85  
E on 38th St  
E 1.6miles location on north of road  
**Submitted By:** Mathew Rothstein      **Affiliation:**  
**Address:** 2225 W Villard St  
**City:** Dickinson      **State:** ND      **Zip:** 58601

## Received By:

**Contact Person:** Mathew Rothstein  
2225 W Villard St  
Dickinson, ND 58601

**Distance Nearest Occupied Building:**      Miles      **Release Contained:** Yes

**Type of Incident:** Low Pressure Frac Line

**Description of Released Contaminant:** X-Link Fluid

**Volume Spilled:** 30.00 barrels      **Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** Unknown

## Cause of Incident:

Failed 4" Butterfly valve

## Risk Evaluation:

None at this time

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

Ground is frozen - allowing X-Link fluid to remain at surface; vac truck siphoned off residue. No impact to any water source.

## Action Taken or Planned:

Shut down operations - cleaned up with Vac Truck (Hell Creek Environmental Services)

**Wastes Disposal Location:** Unknown at this time

## Agencies Involved:

## ***Updates***

---

***Date:*** 3/5/2014    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Roberts, Kris

### ***Updated Volume:***

### ***Notes:***

Release from malfunctioning valve, during fracking activities, remained on location. NCIC retains oversight. Report forwarded to NDIC.