

General Environmental Incident Summary

Incident: 3244 **Date/Time Notice:** 3/14/2014 0915 **DEM Incident No:**
Responsible Party: Bridger Transfer Services, LLC
Date Incident: 3/13/2014 **Time Incident:** 1600 **Duration:** 30 days
County: Ward **Twp:** 156 **Rng:** 86 **Sec:** 21 **Qtr:**
Lat: 48.32364 **Long:** -101.74670 **Method:** Navigation quality GPS
Location Description: Bridger Transfer Services, Berthold Station, 8501 296th St NW, Berthold, ND 58718

Submitted By: David LaMay **Affiliation:** Bridger Employee
Address: 800 Spring Street, suite 205
City: Shreveport **State:** LA **Zip:** 71101

Received By:

Contact Person: Otis Randle
15510 Wright Brothers Dr.
Addison, TX 75001

Distance Nearest Occupied Building: 1 Miles **Release Contained:** Yes

Type of Incident: hose leaking

Description of Released Contaminant: Crude Oil

Volume Spilled: 10.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

Cause of the release is unknown but thought to be an accumulation of minor releases at the truck unloading LACT sites. Melting snow revealed oil runoff and a sheen on standing water from snow melt.

Risk Evaluation:

No immediate Risks

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

No impact to environment due to quick clean up response and complete removal of contaminated material.

Action Taken or Planned:

Release was discovered by field representatives and the clean up contractor United States Environmental Services was notified immediately to perform vacuum and excavation services. All oil stained material was excavated and will be disposed of properly. Backfill soil and gravel will be brought in later today.

Wastes Disposal Location: US Environmental Services will haul and dispose of all waste material at Prairie Disposal Facility

Agencies Involved:

Updates

Date: 3/14/2014 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Volume:

Notes:

According to the incident summary, this spill occurred at a site that is not regulated by the NDIC. Followup is necessary.

Date: 3/26/2014 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Volume:

Notes:

Arrived on location 3/26/14.

No sign of spill at location. Site is appropriately suited for dealing with small incidents such as this.

No followup is necessary.

Date: 6/4/2015 **Status:** Inspection

Author: Kangas, Kathleen

Updated Volume:

Notes:

Arrived on site 06/03/15. No sign of spill. Per Scott's comment, this site is equipped to handle small spills. Closing.