

# General Environmental Incident Summary

**Incident:** 3329      **Date/Time Notice:** 5/27/2014      2      **DEM Incident No:**  
**Responsible Party:** Triple C Services, LLC  
**Date Incident:** 5/26/2014      **Time Incident:**      **Duration:** 4.5 hours  
**County:** Williams      **Twp:** 155      **Rng:** 104      **Sec:** 13      **Qtr:**  
**Lat:** 48.24197      **Long:** -104.01160      **Method:** Navigation quality GPS  
**Location Description:** On County RD 57 Between Stedman 1-24H and and the Stedman 3-24H3

**Submitted By:** Crystal Amundson      **Affiliation:** Safety Coordinator  
**Address:** 1098 16th ST SW  
**City:** Sidney      **State:** MT      **Zip:** 59270

## Received By:

**Contact Person:** Crystal Amundson  
1098 16th st sw  
Sidney, MT 59270

**Distance Nearest Occupied Building:**      **Release Contained:** Yes

**Type of Incident:** Vehicle Accident

**Description of Released Contaminant:** about 2 gallons of crude oil and roughly 98 gallons of diesel

**Volume Spilled:** 100.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** Unknown

## Cause of Incident:

Driver pulled over as far as he could and due to all the rain and the soft "shoulder" of the road the trailer started to slide and took the tractor over with it. ( The road is very narrow and slanted to one side)

## Risk Evaluation:

slew water contamination

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 02 - water

## Potential Environmental Impacts:

could be hazardous to local birds that live in the slew that the truck was laying in. and could soak into soil

## Action Taken or Planned:

Called Clean Harbor Spill Response they worked on it all night

**Wastes Disposal Location:** Disposal at Sawyer, ND

**Agencies Involved:** State Highway Patrol

## **Updates**

---

**Date:** 5/27/2014    **Status:** Inspection

**Author:** Espe, Brady

### **Updated Volume:**

#### **Notes:**

The weather was 81 °F, clear, with wind from the northwest 1-15 mph. The accident occurred on the south side of the road. There is a small creek that flows by this site. There is a culvert under the road at the accident site. The cleanup company placed two booms downstream of the accident. The creek currently is flowing to the west. The creek has numerous cattails. The cleanup has already been done. I did not see any sheen on the water near the booms and accident site. No further followup is needed at this time.

---

**Date:** 5/27/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

### **Updated Volume:**

#### **Notes:**

Crude oil tanker accident. Rolled into a slough. Oil and Gas inspector first on scene and called NDDoH. NDDoH inspector deployed for followup.