

# General Environmental Incident Summary

**Incident:** 3379      **Date/Time Notice:** 7/10/2014      1030      **DEM Incident No:**

**Responsible Party:** Missouri Basin Well Service

**Date Incident:** 7/9/2014      **Time Incident:** 2151      **Duration:**

**County:** McKenzie      **Twp:** 150      **Rng:** 97      **Sec:** 20      **Qtr:**

**Lat:** 47.25210      **Long:** -103.21360      **Method:** Interpolation from map

**Location Description:** The spill occurred from a rollover across the street from Power Fuels, their address is 3711 4 Ave NE Watford City ND 58854. The spill occurred across highway 23 in the ditch

**Submitted By:** Joshua Staggs      **Affiliation:** Environmental Inspector for Missou

**Address:** 12980 35th ST SW

**City:** Belfield

**State:** ND

**Zip:** 58622

## Received By:

**Contact Person:** Lewy Leathers  
12980 35th ST SW  
Belfield, ND 58622

**Distance Nearest Occupied Building:**

**Release Contained:** Yes

**Type of Incident:** Vehicle Accident

**Description of Released Contaminant:** Production Water

**Volume Spilled:** 5.00 barrels

**Ag Related:** No

**EPA Extremely Hazardous Substance:** No

**Reported to NRC:** No

## Cause of Incident:

Truck did not slow down in time causing him to stop too quick and he swerved to avoid contact with another vehicle turning and he rolled over causing his tank to leak and production water released.

## Risk Evaluation:

None

**# of Fatalities:** 0

**# of Injuries:** 0

**Affected Medium:** 03 - soil

## Potential Environmental Impacts:

Soil in the ditch off the highway.

## Action Taken or Planned:

The spill was contained by field safety officer from MBI then the next morning SM Fencing dug the contaminated area and then some out of the ditch and hauled it to a MBI disposal.

**Wastes Disposal Location:** The recovered waste will be disposed of at the Knudston SWD just north of Fairfield, ND

**Agencies Involved:** Local Law Enforcement, Local Emergency Manager

## **Updates**

---

**Date:** 7/10/2014    **Status:** Inspection

**Author:** Espe, Brady

### **Updated Volume:**

#### **Notes:**

The weather was 72°F, cloudy, with wind from the southwest 5 to 10 miles per hour. The area has been cleaned up and graded. The bottom of the ditch to the west had some moist soil that appears to be from recent rains. I did not smell anything. I talked to personnel from the company who indicated that the cleanup crew dug 5 inches below the impacted soil. Further followup is needed to check on vegetation growth.

---

**Date:** 7/10/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

### **Updated Volume:**

#### **Notes:**

Release into a road ditch from a vehicle accident. Followup is necessary.

---

**Date:** 8/13/2014    **Status:** Inspection

**Author:** Espe, Brady

### **Updated Volume:**

#### **Notes:**

The weather was 88 °F, clear, with wind from the southeast 20-25 mph. The ditch has been ripped up and is being re-graded as part of road construction on the highway that has recently started. No further follow-up is needed at this time.