

General Environmental Incident Summary

Incident: 3440 **Date/Time Notice:** 8/29/2014 1530 **DEM Incident No:**

Responsible Party: Emerald Oil, Inc.

Date Incident: 8/27/2014 **Time Incident:** 0300 **Duration:** 2 minutes

County: McKenzie **Twp:** 149 **Rng:** 102 **Sec:** 25 **Qtr:** NW NW

Lat: 47.70301 **Long:** -103.68800 **Method:** Navigation quality GPS

Location Description:

PROCEED IN AN SOUTHERLY DIRECTION FROM ALEXANDER, NORTH DAKOTA ALONG ND-200/US-85 APPROXIMATELY 2.6 MILES TO THE JUNCTION OF THIS ROAD AND ND-86 W TO THE SOUTH; TURN RIGHT AND PROCEED IN A SOUTHERLY, DIRECTION APPROXIMATELY 7.1 MILES TO THE JUNCTION OF THIS ROAD AND 20TH STREET NW TO THE WEST, TURN RIGHT AND PROCEED IN A WESTERLY DIRECTION APPROXIMATELY 1.9 MILES TO THE BEGINNING OF THE PROPOSED ACCESS TO THE SOUTH; FOLLOW ROAD FLAGS IN A SOUTHERLY DIRECTION APPROXIMATELY 181' TO THE PROPOSED LOCATION. TOTAL DISTANCE FROM ALEXANDER, NORTH DAKOTA TO THE PROPOSED WELL LOCATION IS APPROXIMATELY 11.6 MILES.

Submitted By: Rachael Overbey

Affiliation: Emerald Oil Staff

Address: 1600 Broadway

Suite 1360

City: Denver

State: CO

Zip: 80202

Received By:

Contact Person: David Veltri
1600 Broadway
Suite 1360
Denver, CO 80202

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Tank Leak

Description of Released Contaminant: 1 barrel of oil

Volume Spilled: 1.00 barrels

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: No

Cause of Incident:

Thief was left open during night pick up; gas kick caused burping in tank and oil was released through hatch.

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 09 - other

Potential Environmental Impacts:

None

Action Taken or Planned:

Spill was within containment on liner. Power washed tanks. Oil was hydrovac'd out and cleaned up.

Wastes Disposal Location: Trucked to disposal

Agencies Involved:

Updates

Date: 8/29/2014 **Status:** Reviewed - Follow-up Required **Author:** Stockdill, Scott

Updated Volume:

Notes:

According to the incident summary, this spill impacted the surrounding location. Followup is necessary.

Date: 9/10/2014 **Status:** Inspection **Author:** Cooper, Mike

Updated Volume:

Notes:

Weather: 45 F, wind from the NE 5-10 mph, overcast. Spill was contained inside of the berm. There was some excess that had escaped under the berm about 2-3 feet to the west. Did not see anything that had left the site. No more follow-up is needed at this time.