

# General Environmental Incident Summary

**Incident:** 3493    **Date/Time Notice:** 10/9/2014    0533    **DEM Incident No:**  
**Responsible Party:** Superpumper  
**Date Incident:** 10/7/2014    **Time Incident:** 0800    **Duration:** 2 minutes  
**County:** Stark    **Twp:** 140    **Rng:** 99    **Sec:** 33    **Qtr:**  
**Lat:** 46.89553    **Long:** -103.18950    **Method:** Interpolation from map  
**Location Description:** 804 HWY 85 North

**Submitted By:** Kris Wolla    **Affiliation:**  
**Address:** 100 27th Street NE  
**City:** Minot    **State:** ND    **Zip:** 58702-1847

## Received By:

**Contact Person:** Kris Wolla  
100 27th Street NE  
P.O. Box 1847  
Minot, ND 58702-1847

**Distance Nearest Occupied Building:** 200 Feet    **Release Contained:** Yes

**Type of Incident:** Tank Overflow

**Description of Released Contaminant:** Diesel

**Volume Spilled:** 190.00 gallons    **Ag Related:** No

**EPA Extremely Hazardous Substance:** No    **Reported to NRC:** Unknown

## Cause of Incident:

Tank was being filled and overflowed

## Risk Evaluation:

No risk

**# of Fatalities:** 0    **# of Injuries:** 0    **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

May have leached below concrete

## Action Taken or Planned:

Cleaned interior of Dike with Floor Dry

**Wastes Disposal Location:** Dumpster

**Agencies Involved:** Carl Ness

## **Updates**

---

**Date:** 10/9/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

### **Updated Volume:**

#### **Notes:**

Diesel tank overflow inside secondary containment. Report indicates possibility of fuel seeping below concrete. Please follow up and determine situation.

---

**Date:** 1/6/2015    **Status:** Inspection

**Author:** Espe, Brady

### **Updated Volume:**

#### **Notes:**

I arrived at the site at 3:30 p.m. The area received snow yesterday. Overcast with winds from the northwest 10 mph with a temperature 3 °F. The tank area looks clean; there is some snow within the containment. The containment is surrounded by gravel parking lot. Could not see anything in the parking lot area; it is covered by compacted snow. More followup needed. 46.893167; - 103.188650

---

**Date:** 6/4/2015    **Status:** Inspection

**Author:** Espe, Brady

### **Updated Volume:**

#### **Notes:**

I arrived at the site at 10:27 a.m. Raining, 48°F, with the wind from the east 5-10 mph. I could not see anything in the parking lot area around the tanks. The area does slope to the south. No further followup needed at this time.