

# General Environmental Incident Summary

**Incident:** 3526      **Date/Time Notice:** 8/2/2014      **DEM Incident No:**  
**Responsible Party:** RES Americas  
**Date Incident:** 8/2/2014      **Time Incident:**      **Duration:** 15 minutes  
**County:** Rolette      **Twp:** 163      **Rng:** 69      **Sec:** 16      **Qtr:**  
**Lat:** 48.94976      **Long:** -99.59825      **Method:** Interpolation from map  
**Location Description:** At the entrance of turbine 58 (0.5 mi East of County Road 23)

**Submitted By:** Shabeeb Abdul Khader      **Affiliation:** Environmental Supervisor  
**Address:** 10707 52nd Ave  
**City:** Rolla      **State:** ND      **Zip:** 58367

## Received By:

**Contact Person:** Shabeeb Abdul Khader  
10707 52nd Ave  
Rolla , ND 58367

**Distance Nearest Occupied Building:** 0.5 Miles      **Release Contained:** Yes

**Type of Incident:** Hydraulic line leak

**Description of Released Contaminant:** No. hydraulic fluid.

**Volume Spilled:** 0.20 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** Unknown

## Cause of Incident:

Wear on the hydraulic fluid pipe connecting the bucket of the excavator.

## Risk Evaluation:

None

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

None

## Action Taken or Planned:

Vehicle removed from operation and repaired. The spill was contained using diapers and the soil removed to a special waste bin, after the equipment was fixed.

**Wastes Disposal Location:** Special waste bin on the laydown yard of the project.

## Agencies Involved:

## **Updates**

---

**Date:** 8/2/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Volume:**

**Notes:**

Small volume of hydraulic oil leak. No on-site inspection necessary. However, determine why this report was received by email on Nov 2, 2014.

---

**Date:** 3/30/2015    **Status:** Inspection

**Author:** O'Gorman, Brian

**Updated Volume:**

**Notes:**

Visited with the company contact and observed the site on 11/6/2014. Contact showed me the release areas documented by incident reports. Company contact also showed me pictures of releases and cleanup of releases. Pictures showed an area approximately 3 feet in width by 3 feet in length, surrounded by oil-absorbent booms. According to the contact, the soil was shoveled up by personnel and moved to the special waste bin for proper disposal. Due to low volume of spill amount, on-site inspection, and personal communications with the company contact, the area impacted was not visible during the inspection and would appear to have been appropriately cleaned up. No further followup at this time.