

# General Environmental Incident Summary

**Incident:** 3534      **Date/Time Notice:** 11/5/2014      **DEM Incident No:**  
**Responsible Party:** Super Pumpers  
**Date Incident:** 10/31/2014      **Time Incident:** 06:33      **Duration:** 2 minutes  
**County:** McKenzie      **Twp:** 150      **Rng:** 99      **Sec:** 24      **Qtr:**  
**Lat:** 47.79848      **Long:** -103.28430      **Method:** Interpolation from map  
**Location Description:** Rolfson Oil LLC 202 3rd Ave SW Watford City, ND

**Submitted By:** Matt Brenner      **Affiliation:**  
**Address:** 2000 East Burdick Exp  
Suite B  
**City:** Minot      **State:** ND      **Zip:**

**Received By:**

**Contact Person:**  
100 27th St NE  
Minot, ND

**Distance Nearest Occupied Building:** 100 Feet      **Release Contained:** Yes

**Type of Incident:** Tank Overflow

**Description of Released Contaminant:** Clear Diesel Fuel

**Volume Spilled:** 75.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** Unknown

**Cause of Incident:**

Driver overflowed bulk tank 2a.

**Risk Evaluation:**

None, contained in onsite containment

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

None, contained in onsite containment

**Action Taken or Planned:**

Spill was contained by onsite containment. Floor dri was placed down. A Rolfson employee will do the remediation of the soil and floor dri.

**Wastes Disposal Location:**

**Agencies Involved:**

## **Updates**

---

**Date:** 11/5/2014    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

### **Updated Volume:**

#### **Notes:**

According to the incident summary, this spill stayed within containment on location. However, more followup is necessary to determine if areas outside of the containment were impacted.

---

**Date:** 5/12/2015    **Status:** Inspection

**Author:** Espe, Brady

### **Updated Volume:**

#### **Notes:**

I arrived at the site at 10:08 a.m. The weather was cloudy, 43°F, with the wind from the southeast 10-20 mph. The company is working on dismantling the facility. The tanks have their bottom covers removed. There is some water in the containment; I could not see any fuel.    47.79842; -103.28508